

ILLEGIB

25X1D

Approved For Release 2001/08/15 : CIA-RDP69B00041R002600090003-9

Next 1 Page(s) In Document Exempt

Approved For Release 2001/08/15 : CIA-RDP69B00041R002600090003-9

23/11/25

CCJ

(4)

23/1145
aet

24 HOUR GENERATION CHECKLIST

Approved For Release B2016/05/15 : CIA-RDP62B002600090003-9

DEC 127

ITEM	TASKS REQUIRED	H-HOUR START	H-HOUR COMP	ACTUAL TIME COMP	TIME COMP		CP CALLED	
					PRI	SEC	PRI	SEC
1	MAINTENANCE ALERTED		H-24	0730				
2	DCM MEETING		H-23	0830				
3	MAINT SECURE NITROGEN, OXYGEN		H-23	0830				
4	PCL SECURE TRUCKS		H-23	0830				
5	START MISSION AIRCRAFT PREFLIGHT	H-22:30	H-00:30	0750				
6	RECEIVE FUEL LOAD FROM FLIGHT PLANNING		H-22:30	0900				
7	RECEIVED 25X1A		H-22	0930				
8	TEB AND REFUEL	H-22	H-19	1630	1400	1800	1440	2100
9	ARC-50 CODES RECEIVED		H-22	1325				
10	COMMO AND IFF PREFLIGHT	H-22	H-18	1335	1100	1415		
11	SELECT RECOVERY CREW AND GIVE TO DCM	H-20	H-16	1925				
12	INS PREFLIGHT	H-16	H-16	1935				
13	ENG PREFLIGHT	H-16	H-13	2325	1130	1340	1405	1405
14	PACKAGE DATA RECEIVED		H-13:45	2030	1530	1630	1545	1630
15	PACKAGE LOADED (CALL SECURITY BEFORE MOVING PACKAGE)	H-13	H-08:30	2325				
16	SIP AND SYSTEM VI CHECKOUT	H-13	H-0830	2325				
17	POL SEND 25X1A		H-10:45	0040				
18	LOX TOP OFF	H-4	H-03:30	0735	1000			
19	NITROGEN TOP OFF	H-4	H-03:30	0735	2000			
20	AIRCRAFT STATUS BRIEF: CC, INS, EWS, PKG & DCM	H-03:30	H-3	0735				
21	START INS WARMUP		H-03:30	0735				
22	INSTALL CSC MAGAZINE IN NOSE	H-03:30	H-3	0835				
23	INS DATA TAPE LOADING	H-02:30	H-2	0935				
24	PACKAGE I HELIUM PURGE Q-BAY	H-2	H-00:30	1055				
25	PERSONAL EQUIPMENT LOADED	H-02:15	H-2	0935				
26	MAINT CALL SECURITY TO STERLIZE COCKPIT	H-2	H-01:50	0935				
27	COCKPIT SET UP PER CODE SHEET		H-01:50	0935				
28	VIEW-FINDER LOADED WITH FILM	Approved For Release 2001/08/15 : CIA-ORIGR69		0935				
29	ENGINEER CHECK AIRCRAFT	H-01:30	H-1	1025				

24 HOUR GENERATION CHECKLIST (CONT'D) MISSION NUMBER H-HOUR PRI SEC Approved For Release 2001/08/15 : CIA-RDP69B00041R002600090003-9


ITEM	TASKS REQUIRED	H-HOUR START	H-HOUR COMP	ACTUAL TIME COMP	TIME COMP		C.P. CALLED	
					PRI	SEC	PRI	SEC
30	ENGINE START		H-00:30	1123 0700				
31	TAXI		H-00:20	1105 0710				
32	RECOVERY GEAR IN PLACE		H+1	1335 0835				
	POST MISSION LANDING CHECKLIST							
1	LAND AND COOL AIRCRAFT	L+00:00	L+00:30					
2	SECURE ACFT AND SERVICE ENG OIL	L+00:30	L+01:15					
3	REMOVE SCDM TAPE AND GIVE TO SIP	L+00:30	L+01:15					
4	REMOVE VIEWFINDER FILM STRIP AND MAPS	L+00:30	L+01:15					
5	REMOVE BLUE BAG TAPE	L+00:30	L+01:15					
6	MAINTENANCE DESBRIEF	L+00:45	L+01:15					
7	REMOVE INSTRUMENTATION PACKAGE	L+01:00	L+01:15					
8	MOVE ARTICLE INTO HANGAR	L+01:15	L+01:30					
9	DOWNLOAD PKG (NOTIFY SECURITY TO CLOSE HANGAR DOORS)	L+02:30	L+02:30					
10	SCDM DATA TO DCOM FOR [REDACTED] 25X1A		L+03:30					
11	SIP DATA TO DCO		L+04:15					
12	"TAKE" TO SUPPLY (NOTIFY SECURITY BEFORE MOVING TO SUPPLY)		L+05:00					
13	PACKAGE SUBMIT [REDACTED] 25X1A		L+05:00					
14	BD II TAPE TO SECURITY		L+05:00					
15	INS/SCDM TAB RUN TO SECURITY		L+05:00					
16	SCDM TAPE TO SECURITY		L+09:00					
17	INS SUBMIT [REDACTED] 25X1A		L+10:00					

Next 5 Page(s) In Document Exempt

BX 6741 (23 DEC)

RECOVERY CREW

25X1A



25X1A

COCKPIT CREW: 129

127



I C PRIMARY ARTICLE 129

I F SECONDARY ARTICLE 127